




Expert Controller Plus

Version 1.0.1

RELEASE NOTE

Rev. 1

System Requirements

Expert Controller Plus has the following system requirements:

- macOS 14, 15, 26 or later
- SPE Expert 1K-FA Series II or Series III
- SPE Expert 1.3K-FA, SPE Expert 1.5K-FA, SPE Expert 1.5K-Taurus or SPE Expert 2K-FA Amplifier
- USB or RS-232 wired connection between the SPE Expert amplifier and Mac or
- USB or RS-232 wired connection between an SPE Expert amplifier and USB/RS-232 to TCP/IP network adapter.

Expert Controller Plus was designed in 2025 for macOS 14 and later versions. However, the feature that permits windows to float on the desktop requires at least macOS 15.

Additions/changes

- a) Unused configuration (Entitlements) removed.
- b) A single minor bug fix not impacting any user features/capabilities.

Availability

Immediate - via the Apple App Store

Known Issues

- a) None.